




- 1 SET HEAT ANTICIPATOR AT .6 A
- 2 FOR 208V OPERATION MOVE THIS WIRE TO 208V TRANSFORMER TAP
- 3 ADD JUMPER Rc - Rh

MODEL	A RUN CAPACITOR	B FAN CAPACITOR	C CIRCUIT BREAKER
WAG30A-A54C	35 / 370	5 / 370	35A
WAG36A-A54C	40 / 370	10 / 370	40A
WAG40A-A54C	40 / 440	10 / 370	50A

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	---
High Voltage	—	---

USE COPPER OR
ALUMINUM WIRE

4085-158 A

**DANGER: ELECTRICAL SHOCK HAZARD,
DISCONNECT POWER BEFORE SERVICING**