


DANGER: ELECTRICAL SHOCK HAZARD,
DISCONNECT POWER BEFORE SERVICING

MOTOR SPEED COLOR CODE		
COLOR	4 SPEED	3 SPEED
BLUE	MED. HIGH	MED.
RED	MED. LOW	LOW
ORANGE	LOW	—
BLACK	HIGH	HIGH
WHITE	COMMON	COMMON



1 SET HEAT ANTICIPATOR AT .8 A
FOR ALL THERMOSTATS.

△ 2 ADD JUMPER Rc - Rh

IF ANY OF THE ORIGINAL WIRE AS SUPPLIED WITH THE APPLIANCE MUST BE REPLACED, IT MUST BE REPLACED WITH WIRING MATERIAL HAVING A TEMPERATURE RATING OF AT LEAST 105° C. EXCEPT THE IGNITION CABLE WHICH IS 250° C. HIGH VOLTAGE CABLE.