




	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

WPV 53 B
WPV 62 B
WALL THERMOSTAT/OPTIONAL CW45
FIELD WIRING CONNECTIONS