

*ELECTRICAL SHOCK HAZARD
*DISCONNECT POWER BEFORE
SERVICING.

USE COPPER CONDUCTORS
ONLY SUITABLE FOR AT LEAST
75° C.

12 PIN
10 Mont Plug

1 5 2 8 7 6 3 9

3 2 1

Plug #2



*Note: See Control Wiring Section of Installation Inst.
for Wiring Energy Recovery to Unit*

Ladder Diagram

4056-315