





LADDER DIAGRAM

4100-105 C

- ⚠️ Labeled wires connect if no options used.
- ⚠️ Move red wire to 208V tap for 208V operation
- ⚠️ Install jumper for high speed blower oper. on models 36 & 42

⚠️ Remove jumper when LAC is installed

	WIRING CODE		
	FACTORY STD.	FIELD	OPTIONAL
HIGH VOLTAGE			
LOW VOLTAGE			
ACCESSORY			

COLOR CODE			
BK	BLACK	PK	PINK
BL	BLUE	PR	PURPLE
BR	BROWN	R	RED
G	GREEN	T	TAN
O	ORANGE	Y	YELLOW