



Bard Mfg. Co.
Bryan, Ohio

4100C316 A

!

WARNING

USE COPPER CONDUCTORS
ONLY SUITABLE FOR AT LEAST
75° C.

!

DANGER

*ELECTRICAL SHOCK HAZARD
*DISCONNECT POWER BEFORE
SERVICING.

	Factory	Field	Optional
High Voltage		-----	-----
Low Voltage		-----	-----

Composite Wiring Diagram QH Series 3 460-60-3, Represents Max. KW Electric Heat

- A

B

C

D
- Labeled wires connect if no options used.
- F
- Install jumper for hi speed blower oper. on models 36, 42, 48, and 60.
- H
- Remove jumper when Low Amb. Bypass is installed.
- J
- Remove jumper when CS2000A Energy Monitor is installed.

