Bard Mfg. Co.
Bryan, Ohio

4100C319 E

WARNING
USE COPPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 75° C.

DANGER
*ELECTRICAL SHOCK HAZARD
*DISCONNECT POWER BEFORE SERVICING.

Composite Wiring Diagram QH Series 3 460-60-3, Represents Max. KW Electric Heat

	Factory	Field	Optional
High Voltage	———	- - - -	— - —
Low Voltage	———	- - - -	— - —

A B C D Labeled wires connect if no options used.
E Move Red wire to 208V tap for 208V operation.
F Install jumper for hi speed blower oper. on models 36, 42, 48, and 60.
H Remove jumper when Low Amb. Bypass is installed.
J Remove jumper when CS2000A Energy Monitor is installed.