





MODEL	W / ERV	NO ERV
QW2S	5	3.2
QW3S	5	3.2
QW4S	7	3.2
QW5S	7	5

STEPDOWN
TRANSFORMER
CLASS CC FUSE

! DANGER
*ELECTRICAL SHOCK HAZARD
*DISCONNECT POWER BEFORE
SERVICING.



99 Wire Identification numbers for Bard use only.

! WARNING
USE COPPER CONDUCTORS
ONLY SUITABLE FOR AT LEAST
75° C.

	Factory	Field	Optional
High Voltage			
Low Voltage			

Bard
SINCE 1964
Bard Mfg. Co.
Bryan, Ohio
4113-301 A