







COMPOSITE WIRING DIAGRAM QW DEHUMIDIFICATION SERIES 2 230/208/60-1, REPRESENTS UNIT WITH CIRCUIT BREAKER KIT.



COMPONENT CODE	
CB1	CIRCUIT BREAKER #1
CB2	CIRCUIT BREAKER #2
CC	COMPRESSOR CONTACTOR
CCM	COMPRESSOR CONTROL MODULE
COMP	COMPRESSOR
CRC	COMPRESSOR RUN CAPACITOR
FB	FUSE BLOCK
GND	GROUND
HPC	HIGH PRESSURE CONTROL
HS1	HEAT STRIP #1
HS2	HEAT STRIP #2
IBM	INDOOR BLOWER MOTOR
LPB	LOW PRESSURE BYPASS
LPC	LOW PRESSURE CONTROL
OFM	OUTDOOR FAN MOTOR
OMR	OUTDOOR MOTOR RELAY
P1	ACCESSORY PLUG #1
P2	ACCESSORY PLUG #2
P3	ACCESSORY PLUG #3
PLI	PRESSURE LOCKOUT INDICATOR
PM	PHASE MONITOR
RAT	RETURN AIR TSTAT
RLB	RELAY LOGIC BOARD
RV	REV. VALVE SOLENOID
T1	TRANSFORMER #1
T2	TRANSFORMER #2
TB1	TERMINAL BLOCK #1
TB2	TERMINAL BLOCK #2
TB3	TERMINAL BLOCK #3
TB4	TERMINAL BLOCK #4
TB5	TERMINAL BLOCK #5
TB6	TERMINAL BLOCK #6
TB7	TERMINAL BLOCK #7
TWV	THREE WAY VALVE

	LABELLED WIRES CONNECT IF NO OPTIONS USED.
	MOVE RED WIRE TO 208V TAP FOR 208V OPERATION
	INSTALL JUMPER FOR HIGH SPEED BLOWER OPER. ON MODELS 36 & 42

	REMOVE JUMPER WHEN LAC IS INSTALLED
--	-------------------------------------

WIRING CODE			
	FACTORY STD.	FIELD	OPTIONAL
HIGH VOLTAGE			
LOW VOLTAGE			
ACCESSORY			

COLOR CODE			
BK	BLACK	PR	PINK
BL	BLUE	R	PURPLE
BR	BROWN	T	RED
G	GREEN	Y	TAN
GY	GRAY		YELLOW
O	ORANGE		

QW-DA
4100C115
10-1-02

"E", "F", and "G" ARE FACTORY WIRED THERMOSTAT OPTIONS